

# VEHICLE INSPECTION REPORT

**MK15WHS**

## Ford Transit 350 2.2 TDCI 120PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 27/03/2015

Year 2015

Mileage 191,764 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0DXXTTGDEB88679

Body Style Dropside L3

MOT Due 26/03/2026

CAP Clean £2,750.00

CAP Average £2,250.00

CAP Below £1,575.00

Gearbox MANUAL

Gears 6

Tail Lift Column

\*WARNING LIGHTS ON DASH\* AD BLUE

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Digital radio
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



2: Bonnet  
Chipped  
Multiple Chips





3: Other  
N/A  
N/A



4: Other  
N/A  
N/A



5: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



6: Door Mirror Assy nsf  
Broken  
Replace



7: Flasher Side Repeater ns  
Broken  
Replace



8: Door Mirror Glass ns  
Broken  
Replace



9: Moulding nsf Wing  
Scuffed (Unpainted)  
Over 100mm



10: Door Moulding nsf  
Scuffed (Unpainted)  
UpTo 100mm



11: Door Moulding nsf  
Missing  
Replace



12: Door nsf  
Scratched  
UpTo 25mm Thru Paint



13: Other  
N/A  
N/A



14: Other  
N/A  
N/A





15: Other  
N/A  
N/A



16: Door osf  
Scratched  
UpTo 25mm Thru Paint



17: Door Mirror Glass os  
Missing  
Replace



18: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



19: Seat Base Cover osf  
Burn  
Over 3mm



20: Carpets Front  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK